



PARTS DEPARTMENT BULLETIN

DATE: 19-Mar-13

BULLETIN NUMBER: 2013-1

SUBJECT: Parts List 32139 and 36776: Intake and Exhaust Valve Diameter Change

DETAIL: Models Affected: W18, W21, W21A, W27, W27A, 35B Three, 38B Four, 4.5 BCD, 5.8 WMD, 6.0 WMD, 6.0 BCD, 6.0 BTD, 7.5 BTD, 7.7 WMD, 8.0 WMD, 8.0 BTD, 8.3 WMD, 8.3 BTD, 10.0 BTD, 11.0 WMD, 11.0 BTD, 6.0 BTDR, 8.0 BTDR, 7.5 BTDR, 10.0 BTDR, 8.3 BTDR, 11.0 BTDR, 9.4 BTDR and 12.5 BTDR

In late 1991 Parts Bulletin # 65 was published regarding a change made to the intake and exhaust valves on the 42B Four and 12.5 BTDA. In April 2006 a similar Parts Bulletin # 2006-4 for the same models was published and included replacement pages for the appropriate Parts List.

The purpose of this bulletin is to include the additional models listed above which are affected by this same change to the valves.

In order to select the correct valves for any of the models listed above and the 42B and 12.5 BTDA referenced in bulletins # 65 and # 2006-4, the best approach is to measure the original valves and replace them with the same size. Here are the part numbers:

Intake valve: 26.2 MM diameter: P/N 030508
 31.2 - 32.2 MM diameter: P/N 038931

Exhaust valve: 24.2 MM diameter: P/N 030510
 26.2 - 27.2 MM diameter: P/N 038932

WESTERBEKE CORPORATION

Myles Standish Industrial Park, 150 John Hancock Road, Taunton, MA 02780-7319 • Tel: 508.823.7677 • Fax: 508.884.9688

www.westerbeke.com